

HARRY

WE HAD A TUB SKID LEAKING
COENTENT BADLY TONIGHT (STORED
OUTSIDE DOOR 12). I CALLED THE
MAINTENANCE CLEAN UP CREW - THEY
CHECKED IT UP. THEY RECOMMEND THAT
WE REQUEST FACILITIES TO BUILD A
RETAINING CURB AROUND THE TUB
STORAGE AREA TO PREVENT SPILLS FROM
POSSIBLY GETTING INTO THE STORM DRAINS.
HAS THIS BEEN SUGGESTED BEFORE AND
IF NOT SHOULD WE MAKE A REQUEST TO
HAVE A RETAINING CURB INSTALLED?

Douglas

2-28-79